

Additional Photos: 81-23569

#2 Engine



TEMP INSTALL 1.JPG



TEMP INSTALL 2.JPG



TEMP INSTALL 3.JPG






TEMP INSTALL 4.JPG



TEMP INSTALL 5.JPG

Misc Photos





NON PART NO. AND ITEM DESCRIPTION 1615-01-074-8150 70150-09100-043 Blade, Motor Blade		UNSERVICEABLE (REPAIRABLE) TAG - MATERIAL CONDITION CODE F	
SERIAL NO. LOT NO. PART-05048 CONTRACT OR PURCHASE ORDER NO. UNK		QUANTITY 1	
REMOVED FROM 8423969 UH-60L REPAIR OR NAME OF REPAIRING MONROE, LA E.SFC		REASON FOR REPAIRABLE CONDITION Titanium Strip Deformed Beyond Repair Limits	
REPAIRS Debonding / Can top test Failed beyond limits TSP 4831.2 TSD 0 NDI: X			

DD FORM 1677-2, 1 OCT 86

NON PART NO. AND ITEM DESCRIPTION 1615-01-196-1903 70150-09100-043 Blade, Motor Blade		UNSERVICEABLE (REPAIRABLE) TAG - MATERIAL CONDITION CODE F	
SERIAL NO. LOT NO. PART-05048 CONTRACT OR PURCHASE ORDER NO. UNK		QUANTITY 1	
REMOVED FROM UH-60L		REASON FOR REPAIRABLE CONDITION Blade Deformed Beyond Repair Limits	
REPAIRS TSP 5956.5 TSD 0 NDI: X			

<small>WARNING: Unserviceable weapons, including, but not limited to, hand grenades, should be destroyed by a tag of this type. This tag must be attached to a tag of this type. (18 USC 2381)</small>		UNSERVICEABLE (REPARABLE) TAG - MATERIEL	
PSN, PART NO. AND ITEM DESCRIPTION 1615-01-106-1903 70150-09100-043 NR Blade		INSPECTION ACTIVITY AASF #2 merana	CONDITION CODE F
SERIAL NO. / LOT NO. A007-11880		UNIT OF ISSUE EA	REASON FOR REPARABLE CONDITION SPAR Pak REMOVED FROM UH60L 8323898 INSPECTOR'S NAME OR STAMP AND DATE 21 FEB 20 MORENO, WISE. SFC (M)
CONTRACT OR PURCHASE ORDER NO. UNK		QUANTITY 01	
REMARKS TSN: 3215.4 TSO: ϕ NOH: ϕ		(M)	

DD FORM 1577-2, 1 OCT. 66
U.S. GPO: 1987-186-748

<small>WARNING: Unserviceable weapons, including, but not limited to, hand grenades, should be destroyed by a tag of this type. This tag must be attached to a tag of this type. (18 USC 2381)</small>		UNSERVICEABLE (REPARABLE) TAG - MATERIEL	
PSN, PART NO. AND ITEM DESCRIPTION 1615-01-106-1903 70150-09100-043 Main Zone Blade		INSPECTION ACTIVITY AASF #2 AZ	CONDITION CODE F
SERIAL NO. / LOT NO. A007-11996		UNIT OF ISSUE EA	REASON FOR REPARABLE CONDITION 3" CRACK NEAR BLADE CUFF 2 1/4 - 2 1/2" CRACK NEAR TIP CAP REMOVED FROM UH-60L = 8321 INSPECTOR'S NAME OR STAMP AND DATE 25 SEP 18 MORENO, WISE. SFC (M)
CONTRACT OR PURCHASE ORDER NO. UNK		QUANTITY 1	
REMARKS SH2A000		TSN: 3516 TSO: ϕ NOH: ϕ	

DD FORM 1577-2, 1 OCT. 66